	UI	4	ω			2		ы			0			11			10	u	00	7	ı.	6	5	4	•		w 2		н	c	Bit	-
	22	21	20			19		100			17			12		1	11	5	9	00	•	7	σι	u	1		w 4		2	۳		PS-MPPT
	Heatsink Over-Temperature	Load HVD	Software bug			Load MOSFETs damaged		Load Over-current			Load Fault External Short Circuit			DIP Switch Changed (excl. DIP 8)			Slave Control Timeout	pattery LVD	Local Temp. Sensor Failed	RTS disconnected		RTS shorted	EEPROM setting edit (reset required)	Array nvo			Software bug Battery HVD		FETs shorted	Overcurrent	Array Fault	PT
														Blink R			Blink R	o o	Solid R	Solid K	0	Solid R	Solid R				Solid R Blink R		Solid R	JOHO Z	Status	LED Indication
	R-Y	R-G	R-Y-G			R-Y-G		R/Y-G			R/G-Y			R-Y-G						K/Y-G/Y	S	R/Y-G/Y	R-Y-G								Status	lication
disconnected	Heatsink temperature exceeds safe operating limits - load	Battery voltage exceeds load high voltage disconnect threshold	A software error has occurred in the processor			Load MOSFETs shorted		Load current draw exceeds the controllers rating			External wiring short circuit			DIP switch changed while running			Slave mode charging control has timed-out	halt to charging possible		properly connected)		Short circuit detected in Remote Temp Sensor	EEPROM settings edited while running	LA HITTORY AND			A software error has occurred in the processor Battery voltage exceeds high voltage disconnect threshold		MOSFET(s) damaged - short circuited	The claige chilette exceeds the chilinities a fathlight		
Excessive ambient temperature	Poor airflow around controller	Another charging source in the system is over-charging the battery	This is an internal software problem	A power MOSFET is damaged (short circuited)	An external short has occurred	Voltage on the Load terminals	Damaged load causing excessive current draw	Load draws more than SSMPPT rated current	Damaged load causing excessive current draw	A system miswire	A short occurred on a power cable	Dirt/Debris/Condensation	DIP switch(s) not fully in on/off position	User changed a DIP switch during operation	Controller has not received a slave command in over 60 seconds		Loss of communications with controller	Control of the contro		present.	are causing an erroneous reading The BTS is no longer detected Previously a valid RTS signal was	The RTS cable has been pinched or otherwise shorted The RTS terminal connections have collected dust/moisture and	A set point was changed via custom programing	0	Power MOSFETs may be shorted Array input voltage exceeds operational ratings	battery	This is an internal software problem Another charging source in the system is over-charging the	An external short has occurred	The current sense circuitry is malfunctioning A power MOSFET is damaged (short circuited)	A China And an inches	Causes	
on all sides. See manual for more information. Check ambient temperature at the controller location. Ensure temperature is below maximum temp rating of SSMPPT. See	Ensure controller is mounted in a position with enough clearance	Remove the other charging source, check its operation and charging voltage. Keep the charging voltage at or below the could be charging voltage.	Update to latest firmware from the Morningstar website	externally Contact distributor for service	Output circuit Be sure the positive power terminals are not wired together	Verify there are no other power sources connected to the load	these loads directly to battery instead. Inspect and test load for proper operation	Reduce loads connected to SSMPPT load terminals. Connect	externally Inspect and test load for proper operation	Be sure the positive power terminals are not wired together	Inspect the system wiring for shorts, damaged insulation, etc.	position Inspect the PCB around the DIP switches for moisture, corrosion,	Check all DIP switches to ensure they are in full 'on' or 'off	Return the DIP switches to original position or reset the PSMPPT so that the new changes take effect.	Check to make sure master device is configured to send slave commands at least once every 60 seconds	master device is still powered and sending commands	this minimum level. Check physical communications connection to controller, check	Resize system as necessary to prevent batteries drained below	Contact distributor for service Consult documentation for minimum battery operating voltage.	for breaks.	alcohol if necessary Inspect the RTS connection for loose wires. Inspect the RTS cable	Inspect RTS cable and connection Inspect RTS terminals for dust/dirt/moisture and clean with	temperature effects on the array Voc. Restart/power cycle to reset. MSView Coil Reset command may	voltage below maximum rating. Be sure to take into account	Symper Charging voltage. Contact distributor for service Consult documentation for maximum array voltage. Keep array	charging voltage. Keep the charging voltage at or below the	Update to latest firmware from the Morningstar website Remove the other charging source, check its operation and	be sure the positive power terminals are not wred together externally	Contact distributor for service		Consult the documentation for maximum current ratings	

17	; t	ń	14	13	12		11	:		10	9			03	09		7		0					л		4		U	N.	2	н		0	Bit	`	1				ח	Bit
18	: 5	7	15	14	L		1	j		Ħ	10				9		00		7					ת		5		4	Δ.	ω	2		ы		1	2			1	23	
FET open	LL TO Arthly One of Marine	EP10 Simply Out of Range	Tb SV (RTS miswire)	Uncalibrated	Battery sense Disconnected		battery sense Out of Nange	Det of Design		Current offset	Current limit				Tind Hot (active temp limiting)		Tind (inductor temp sensor) Short		Tind (inductor temp sensor) Open					Heatsink Hot (active temp limiting)		Ths shorted		Contraction	Theorem	RTS disconnected	RTS shorted		RTS open	Alarm	ELLION Security and Labour sedon seal	second setting adit (reset required)				DIP Switch Changed (excl. DIP 8)	Array Fault
																																				Silia				Blink R	Charging
			R/Y - G/Y		N. G.	2	7	8V.6V																						R/Y-G/Y	R/Y-G/Y					R-Y-G				R-Y-G	Battery
MOSFET(s) damaged - open circuit	still operate correctly, but this is an indication of a potential hardware failure.	Floating 10V internal power supply out-of-range. Unit may Internal hardware problem	and/or voltage readings may result Remote Temp Sensor wired incorrectly	Factory calibration was not performed, inaccurate current	COLETY SELECT WAS ANALYSIES, LICEN CALCULATION (See	ם ביינים	parter & series actively out of accelerate and a	Battery sense voltage out of acceptable range	current, could lead to inaccurate load and/or array current	Erroneous current reading when there should be zero	Active limiting of charging current			current	Inductor high temp. warning, reduction of charging		Inductor temp. sensor short circuit		inductor temp. sensor open circuit				charging current	Heatsink High Temperature Warning, reduction of		Heatsink temp. sensor short circuit			properly connected) Heatsink temp, sensor open circuit	r has been disconnected (was	Short circuit detected in Remote Temp Sensor		Remote Temp Sensor Disconnected (always set if no RTS connected)			FFPROM settings edited while running				DIP switch changed while running	Description
Hardware failure		/ Internal hardware problem	Battery Sense and/or RTS wired incorrectly	: Calibration of measurement circuits not performed at factory	Greater than 5V difference between Sense and Battery Voltage	Disconnected wire on the Rattery Sense	Greater than 5V difference between Sense and Battery Voltage	Disconnected wire on the Battery Sense	Damage to current measurement circuit	Failed current offset routine	Input power exceeds controller rating		Excessive ambient temperature		Poor airflow around controller		Damage to one or more inductor temperature sensors		Dallighe to one of more illeactor temberature sensors	7		Excessive ambient temperature		Poor airflow around controller		Damage to heatsink temperature sensor			Damage to heatsink temperature sensor	See Array Fault: RTS disconnected above.	See Array Fault: RTS shorted above.		RTS not connected			A set point was changed via custom programing	Dirt/Debris/Condensation	DIP switch(s) not fully in on/off position		User changed a DIP switch during operation	Causes
Contact distributor for service		correct polarity Contact distributor for service	Ensure Battery Sense and RTS wired to correct terminals with	power capies and connection. Contact distributor for service.	Inspect Battery sense wires and connection. Inspect Battery	power cables and connection. Inspect Battery Sense connection	Inspect Battery sense wires and connection. Inspect Battery	Inspect Battery Sense connection	Contact distributor for service	Reboot controller and allow sweep of array input. Check if Alarm	No action required, controller will operate at full rated output.	manual for more information.	Check ambient temperature at the controller location, ensure	on all sides. See manual for more information.	Ensure controller is mounted in a position with enough clearance	the inductor temperature from exceeding sare levels. Contact	Without accurate temperature sensor, controller cannot prevent	distributor for service.	the inductor temperature from exceeding safe levels. Contact	Mithout accurate temporature sensor controller cannot prevent	temperature is below maximum temp rating of SSMPP1. See	Check ambient temperature at the controller location. Ensure	on all sides. See manual for more information.	Ensure controller is mounted in a position with enough clearance	distributor for service.	Without accurate temperature sensor, controller cannot prevent	distributor for service.	the heatsink temperature from exceeding safe levels. Contact	Without accurate temperature sensor, controller cannot prevent	See Array Fault: RTS disconnected above.	See Array Fault: RTS shorted above.	for more accurate temperature compensated charging	RTS not required for operation, RTS can be connected if desired		also be used.	Restart/power cycle to reset. MSVIew Coil Reset command may	Inspect the PCB around the DIP switches for moisture, corrosion,	Check all DIP switches to ensure they are in full on or on position	so that the new changes take effect.	Return the DIP switches to original position or reset the PSMPPT	Solutions

	26		25	1	24	23		22			21			20			19				18	Bit
	27		26		25	24		23			22			21			20				19	
	EEPROM Access Failure		Log Timeout		LVD	Power on Reset		high Va current limit			12V Supply Out of Range			3V Supply Out of Range			IL Offset				IA Offset	Array Fault
																						Charging Status
																						Battery Status
	Log data and/or custom charging settings load failure		24hrs since last log entry write		idition has occurred and	A power down reset has occurred	nardware	oltage too high, current limiting to protect	hardware failure.	operate correctly, but this is an indication of a potential	P12 Internal power supply out-of-range. Unit should still	hardware failure.	operate correctly, but this is an indication of a potential	P3 Internal power supply out-of-range. Unit should still	measurement	current, could lead to inaccurate load current	Erroneous current reading when there should be zero		measurement	current, could lead to inaccurate array current	Erroneous current reading when there should be zero	Description
memory	Hardware failure, no access to log data or custom settings	last 24hrs.	Controller has not detected a complete sunrise/sunset cycle in the	disconnect threshold	Battery voltage has dropped below the load low voltage	Controller has lost nower		Array input voltage too high for safe operation			Internal hardware problem			Damage to current measurement circuit Internal hardware problem			Failed current offset routine	Damage to current measurement circuit			Failed current offset routine	Causes
If yes, contact distributor for service.	these factors. Reboot controller (power cycle on/off) and check if Alarm returns.	conditions at night, or miswiring of the solar array. Check all of	Controller has not detected a complete sunrise/sunset cycle in the Could indicate excessively low array voltage, high ambient light	up to a higher level	None required	temperature effects on the array Voc.	voltage below maximum rating. Be sure to take into account	Consult documentation for maximum array voltage. Keep array		A STATE OF THE STA	Contact distributor for service			Contact distributor for service Contact distributor for service		returns	Reboot controller and allow sweep of array input. Check if Alarm	Contact distributor for sension		returns	Reboot controller and allow sweep of array input. Check if Alarm	Solutions