-	ï
- 3	ī
3	ζ
•	τ
•	τ

5 22 Heatsink Over-Temperature	3 20 Software bug 4 21 Load HVD	2 19 Load MOSFETs damaged	1 18 Load Over-current	Load Fault 0 17 External Short Circuit		11 12 DIP Switch Changed (excl. DIP 8)	10 11 Slave Control Timeout	9	6 7 RTS shorted 7 8 RTS disconnected	o	2 3 Software bug 3 4 Battery HVD	1 2 FETs shorted	PS-MPP1  Array Fault  O 1 Overcurrent
						Blink R	Blink R	Solid R Solid R	Solid R	Solid R	Solid R Blink R	Solid R	LED Indication Charging Battel Status Statu Solid R
R -≺	R - Y - G R - G	R-Y-G	R/Y - G	R/G - Y		R - Y - G			R/Y - G/Y	R-Y-G			lication Battery Status
Heatsink temperature exceeds safe operating limits - load disconnected	A software error has occurred in the processor Battery voltage exceeds load high voltage disconnect threshold	Load MOSFETs shorted	Load current draw exceeds the controllers rating	External wiring short circuit		DIP switch changed while running	Slave mode charging control has timed-out	properly connected)  Damaged local (ambient) temp sensor  Battery voltage below minimum operating range, possible halt to charging possible	Short circuit detected in Remote Temp Sensor  Remote Temp Sensor has been disconnected (was	EEPROM settings edited while running	A software error has occurred in the processor  Battery voltage exceeds high voltage disconnect threshold - halt in charging  PV input voltage above safe operating limit	MOSFET(s) damaged - short circuited	Description The charge current exceeds the controller's rating
d Poor airflow around controller Excessive ambient temperature	A power MOSFET is damaged (short circuited) This is an internal software problem Another charging source in the system is over-charging the battery	Damaged load causing excessive current draw Voltage on the Load terminals An external short has occurred	A system miswire  Damaged load causing excessive current draw Load draws more than SSMPPT rated current	A short occurred on a power cable	DIP switch(s) not fully in on/off position	Controller has not received a slave command in over 60 seconds  User changed a DIP switch during operation	Loss of communications with controller		The RTS cable has been pinched or otherwise shorted The RTS terminal connections have collected dust/moisture and are causing an erroneous reading The RTS is no longer detected. Previously a valid RTS signal was	A set point was changed via custom programing	A software error has occurred in the processor  This is an internal software problem  Battery voltage exceeds high voltage disconnect threshold Another charging source in the system is over-charging the battery  - halt in charging  Power MOSFETs may be shorted  Power MOSFETs may be shorted  Array inout voltage exceeds operational ratings	The current sense circuitry is malfunctioning A power MOSFET is damaged (short circuited) An external short has occurred	Causes PV Array is too large
SSMPPT charging voltage.  Ensure controller is mounted in a position with enough clearance on all sides. See manual for more information.  Check ambient temperature at the controller location. Ensure temperature is below maximum temp rating of SSMPPT. See manual for more information.	externally  Contact distributor for service  Update to latest firmware from the Morningstar website  Remove the other charging source, check its operation and  charging voltage. Keep the charging voltage at or below the	Inspect and test load for proper operation  Verify there are no other power sources connected to the load output circuit  Be sure the positive power terminals are not wired together	Be sure the positive power terminals are not wired together externally Inspect and test load for proper operation Reduce loads connected to SSMPPT load terminals. Connect these loads directly to battery instead	Inspect the system wiring for shorts, damaged insulation, etc.	Check all DIP switches to ensure they are in full 'on' or 'off position  Legacratha PCB around the DIP switches for moisture corrosion	Check to make sure master device is configured to send slave commands at least once every 60 seconds  Return the DIP switches to original position or reset the PSMPPT so that the new changes take effect.	The check physical communications connection to controller, check master device is still powered and sending commands	for breaks.  Contact distributor for service  Consult documentation for minimum battery operating voltage.  Resize system as necessary to prevent batteries drained below	Inspect RTS cable and connection Inspect RTS terminals for dust/dirt/moisture and clean with alcohol if necessary Inspect the RTS connection for loose wires. Inspect the RTS cable	voltage below maximum rating. Be sure to take into account temperature effects on the array Voc.  Restart/power cycle to reset. MSView Coil Reset command may also be used.	Update to latest firmware from the Morningstar website Remove the other charging source, check its operation and charging voltage. Keep the charging voltage at or below the SSMPPT charsing voltage.  Contact distributor for service  Consult documentation for maximum array voltage. Keep array	Contact distributor for service Contact distributor for service Be sure the positive power terminals are not wired together externally	Solutions Consult the documentation for maximum current ratings

16 17	15	13	12	10 11	9	00	7	σı	UI	4	3 21	0 Bit	7	6 Bit
17 18	16	14 15	13	11 12	10	φ	00	7	o	, G	4 8 2	ь	24	23
FET open		Uncalibrated Tb 5V (RTS miswire)	Battery Sense Disconnected	Current offset  Battery Sense Out of Range	Current limit	Tind Hot (active temp limiting)	Tind (inductor temp sensor) Short	Tind (inductor temp sensor) Open	Heatsink Hot (active temp limiting)	Ths shorted	RTS shorted RTS disconnected Ths open	Alarm RTS open	EEPROM setting edit (reset required)	Array Fault DIP Switch Changed (excl. DIP 8)
													Solid R	Charging Status Blink R
		R/Y - G/Y	R/Y - G/Y	R/Y - G/Y							R/Y - G/Y R/Y - G/Y		R-Y-G	Battery Status R-Y-G
MOSFET(s) damaged - open circuit	Floating 10V internal power supply out-of-range. Unit may Internal hardware problem still operate correctly, but this is an indication of a potential hardware failure.	Factory calibration was not performed, inaccurate current and/or voltage readings may result Remote Temp Sensor wired incorrectly	Battery sense was working, now out of range	Erroneous current reading when there should be zero current, could lead to inaccurate load and/or array current measurements Battery sense voltage out of acceptable range	Active limiting of charging current	Inductor high temp. warning, reduction of charging current	Inductor temp. sensor short circuit	Inductor temp. sensor open circuit	Heatsink High Temperature Warning, reduction of charging current	Heatsink temp. sensor short circuit	Short circuit detected in Remote Temp Sensor Remote Temp Sensor has been disconnected (was properly connected) Heatsink temp. sensor open circuit	Remote Temp Sensor Disconnected (always set if no RTS connected)	EEPROM settings edited while running	Description DIP switch changed while running
Hardware failure	ay Internal hardware problem	nt Calibration of measurement circuits not performed at factory  Battery Sense and/or RTS wired incorrectly	Disconnected wire on the Battery Sense Greater than SV difference between Sense and Battery Voltage	Failed current offset routine  nt  Damage to current measurement circuit  Disconnected wire on the Battery Sense  Greater than SV difference between Sense and Battery Voltage	Input power exceeds controller rating	Poor airflow around controller  Fixe-skive amhient temperature	Damage to one or more inductor temperature sensors	Damage to one or more inductor temperature sensors	Poor airflow around controller Excessive ambient temperature	Damage to heatsink temperature sensor	See Array Fault: RTS shorted above. See Array Fault: RTS disconnected above. Damage to heatsink temperature sensor	RTS not connected	Dirt/Debris/Condensation A set point was changed via custom programing	Causes User changed a DIP switch during operation DIP switch(s) not fully in on/off position
Contact distributor for service	Contact distributor for service	Contact distributor for service.  Ensure Battery Sense and RTS wired to correct terminals with correct polarity.	Inspect Battery Sense connection. Inspect Battery Sense wires and connection. Inspect Battery sense wires and connection.  Dower-cables and connection.	Reboot controller and allow sweep of array input. Check if Alarm returns Contact distributor for service Inspect Battery Sense connection Inspect Battery sense wires and connection. Inspect Battery	temperature is below maximum temp rating of SSMPPT. See manual for more information. No action required, controller will operate at full rated output.	distributor for service.  Ensure controller is monted in a position with enough dearance on all sides. See manual for more information.  Check arbient temperature at the controller location. Ensure	distributor for service.  Without accurate temperature sensor, controller cannot prevent the inductor temperature from exceeding safe levels. Contact	rempleature is below maximum temp rating or sowiring. See manual for more information.  Without accurate temperature sensor, controller cannot prevent the industry temperature accepting sefs levels. Contact the industry temperature from exceeding sefs levels.	distribution for service.  Ensure controller is mounted in a position with enough clearance on all sides, See manual for more information.  Check ambient temperature at the controller location. Ensure	It is nears in temperature from exceeding safe revels. Collect distributor for service.  Without accurate temperature sensor, controller cannot prevent the heatsink temperature from exceeding safe levels. Contact	See Array Fault: RTS shorted above. See Array Fault: RTS disconnected above. Without accurate temperature sensor, controller cannot prevent	RTS not required for operation, RTS can be connected if desired for more accurate temperature compensated charging	position Inspect the PCB around the DIP switches for moisture, corrosion, debris Restart/power cycle to reset. MSVIew Coll Reset command may also be used.	Solutions  Return the DIP switches to original position or reset the PSMPPT so that the new changes take effect.  Check all DIP switches to ensure they are in full 'on' or 'off

26	23 24 25	22	21	20	19	Bit 18
27 EEPROM Access Failure	24 Power on Reset 25 LVD 26 Log Timeout	23 high Va current limit	22 12V Supply Out of Range	21 3V Supply Out of Range	20 IL Offset	Array Fault 19 IA Offset
						Charging Status
						Battery Status
Log data and/or custom charging settings load failure	A power down reset has occurred Low Voltage Disconnect (load) condition has occurred and the load was disconnected 24hrs since last log entry write		operate correctly, but this is an indication of a potential hardware failure.  P12 Internal power supply out-of-range. Unit should still operate correctly, but this is an indication of a potential		Erroneous current reading when there should be zero current, could lead to inaccurate load current	Description Erroneous current reading when there should be zero current, could lead to inaccurate array current measurement
last 24hrs. Hardware failure, no access to log data or custom settings memon	Controller has lost power  Battery voltage has dropped below the load low voltage  None required  None required  None required  None required condition will recover when battery bank charge disconnect threshold  up to a higher level  Controller has not detected a complete sunrise/sunset cycle in the Could indicate excessively low array voltage, high ambient light	Array input voltage too high for safe operation	Internal hardware problem	Damage to current measurement circuit Internal hardware problem	Damage to current measurement circuit Failed current offset routine	Causes Failed current offset routine
conditions at night, or miswiring of the solar array. Check all of these factors.  Reboot controller (power cycle on/off) and check if Alarm returns.	temperature effects on the array Voc.  None required  None required condition will recover when battery bank charges  up to a higher level  re Could indicate excessively low array voltage, high ambient light	Consult documentation for maximum array voltage. Keep array voltage below maximum rating. Be sure to take into account	Contact distributor for service	Contact distributor for service Contact distributor for service	Contact distributor for service Reboot controller and allow sweep of array input. Check if Alarm returns	Solutions Reboot controller and allow sweep of array input. Check if Alarm returns