11 12 RTS Miswire R/Y	10 11 Uncalibrated	9 10 Batt Sense Disc R/Y	Battery Sense		7 8 Current offset	6 7 Current Limit			4 The Disconnected	o proposition	2 RTS Shorted	Bit Alarm Indi		13 RTS Miswire	11 12 RTS Disconnected	R/Y	10 11 RTS Shorted	9 10 miswire R-	8 9 reset? R-	7 8 Settings Edit R-	77-	5 6 TriStar Hot R 6 7 DIP sw Changed	HVD	4 software	2 3 FET Short R-	2 Overcurrent	1 External Short	Bit Fault Indi
R/Y - G/Y Temp	Factor	R/Y - G/Y	R/Y - G/Y		There off.	An ov	R-Y limits		R/Y-G/Y Heats		Remo R/Y - G/Y	LED Indication	R/Y-G/Y			R/Y - G/Y	A sho	R-Y-G System	R-Y-G A faul	R-Y-G EEPRO	R-Y-G	R-Y The Ti	R-G The b	R-Y-G A soft	R-Y-G MOSF	G-Y/R The d	R/G - Y Hardy	Indication
Temp Sense connection wired incorrectly	Factory calibration was not performed	Battery sense was working, now out of range		Battery sense voltage out of acceptable range	There is a current reading even though the MOSFETs should be off.	An overcurrent condition has put the TriStar into current limit	P. Carrier and C. Car	Heatsink temp sensor short circuit The IniStar heatsink temperature it The IniStar heatsink temperatur	Heateink terms sensor ones circlit	FG.	Remote Temp Sensor not connected Remote Temp Sensor shorted	Description		There is a miswire on the RTS connection	The RTS was properly connected. Now it's not connected.		A short has been detected in the Temp Sense cable	System miswiring detected	A fault was interrupted (usually power-cycle)	EEPROM setting edited while running		The TriStar Heatsink has exceeded acceptable operating DIP switch changed while running	The battery voltage is above acceptable levels	A software error has occurred in the processor	MOSFETs shorted	The charge or load current exceeds the TriStar rating	Hardware detected an external short circuit	Description
<	< < <	\ \	< <		< °	`	4	< <				Diversion Load Charge				\ \ \		`	4 4 4	< < <	< < <	< <	\ \ \	< <	< <	4 4	< <	version Load harge
Battery Sense wired to Temp Sense In	as not performed to trim voltage	Disconnected wire on the Battery Sense In Greater than 5V difference between Sense and Battery In Voltage	Greater than 5V difference between Sense and Battery In Voltage	Damage to internal current measurement circuit Confisconnected wire on the Battery Sense In		Charging current is too high. Ru Diversion load is too large Ru		RTI on the PCB is damaged or shorted CI	otherwise	bense	8	Causes	eaver A series when a row series A series A			There is a miswire on Battery Sense or Temp Sense In	rwise shorted	is voltage on the load terminals when the ETS are turned off	The power was cycled on the TriStar during a fault (any C) fault)	Dirt/Debris/Condensation ir A set point was changed via RS-232 during operation R	DIP switch(s) not fully in on/off position	Power MOSFETs may be shorted R Controller is too hot V User changed a DIP switch during operation R	m is over-charging	Voltage on the Load terminals (Load Mode ONLY) Solar input voltage too low (Charge Mode ONLY) This is an internal software problem U	A power MOSFET is damaged R An external short has occurred B	PV Array is too large, or Load is too large The current sense circuitry is malfunctioning Ti	A short occurred on a power cable Ir A system miswire 8	Causes
Inspect Temp Sense connection	Contact Morningstar for service	Inspect Battery Sense connection Inspect Battery sense wires and connection. Inspect Battery power cables and connection.	Inspect Battery sense wires and connection. Inspect Battery power cables and connection.	Contact Morningstar for service Inspect Battery Sense connection	Refer to the TriStar MOSFET Replacement instructions	oller ersion load sizing	exceed the TriStars operating temperature range.		Inspect the RTS connection and cable	Inspect the KTS and Battery Sense connections		Solutions	IIISPECL (TIE N.1.3 and Battery Sense connections		rection and cable	inspect the RTS and Battery Sense connections	to Load terminals for Load terminals inspect RTS cable and connection		Clears 10sec after startup. Ensures that a power cycle will not clear a fault in less than 10 seconds.	Inspect the PCB around the DIP switches for moisture, corrosion, debris Restart TriStar using MODBUS coil command or power cycle to reset	Check all DIP switches to ensure they are in full 'on' or 'off position	MOSFET Replacement instructions ample wentilation and spacing. Be sure ambient temp does not ches to original position or reset the TriStar so that the new	Remove the other charging source, check its operation and charging set point.	Verify there are no other power sources connected to the load circuit Ensure PV Voc is greater than battery voltage Update TriStar PVM firmware (see Morningstar Website)	Refer to the TriStar MOSFET Replacement instructions Be sure the positive input/output power terminals are not wired together	Consult the TriStar documentation for maximum current ratings TriStar Requires Service or replacement	Inspect the system wiring for shorts, damaged insulation, etc. Be sure the positive input/output power terminals are not wired together	Solutions
							operation					Additional Info	Auto-clears if miswire corrected	unit without RTS to clear fault and	Auto-clears if RTS reconnected: reboot		Auto-clears if short removed	Auto-clears if miswire corrected				Auto-clears if heatsink temp drops to	Auto-clears when battery voltage drops to safe level		Auto-clears if short removed	Auto-clears if PV current drops below controller rating		Additional Info

20 21 Log Timeout	18 19 Power On Reset 19 20 LVD condition	15 16 FET open 16 17 P12 17 18 unused	14 15 miswire	13 14 high d	12 13 HVD	Bit Fault
	et Controller power loss and reboot (daily alarm only) Low Voltage Disconnect occurred (daily alarm only) 24hrs since last log entry write (daily alarm only)	MOSFETs open Internal power supply problem	There is voltage on the load terminals when the MOSFETs are	The TriStar is nearing 100% diversion, beyond which the TriStar can no longer regulate the battery.	Indicates high battery voltage in diversion	LED Description
< < <		< <	Ts are	TriStar		Load
•	✓ ✓ Controller rebooted	Another power source is wheat to the load circuit V Power MOSFIS damaged Dirt/Debris/Condensation on the PCB Damage to internal circuitry	Load is disconnected or damaged Power MOSFETs damaged System wiring problem	Load is disconnected or damaged Power MOSFETs damaged Undersized diversion load/too much charge current	Undersized diversion load/too much charge current	Canses
ambient light is keeping PV voltage high during nighttime, check if	None Required None Required	Verify that the TriStar is the only device wired to the diversion load bank. Refer to the TriStar MOSEET Replacement instructions Inspect the circuits for moisture, corrosion, debris Contact Morningstar for service	Check load wiring and diversion loads Refer to the TriStar MOSFET Replacement instructions Ensure positive input/output terminals are not wired together	Check load wiring and diversion loads Refer to the TriStar MOSFET Replacement instructions Refer to the TriStar operators manual for diversion mode system sizing.	Refer to the TriStar operators manual for diversion mode system sizing.	Solutions
Appears in Daily Alarms only	Appears in Daily Alarms only Appears in Daily Alarms only	with DIP switches In Load/Diversion Mode, load must b Can only be present if battery voltag >13V	Check to ensure Diversion mode sele			Additional Info

ensure Diversion mode selected switches switches be present if battery voltage be present if battery voltage in Daily Alarms only in Daily Alarms only in Daily Alarms only