Contact distributor for service	internal hardware problem	In the land of the		unused	31-32 un	30-31 31	30
		Flash memory read/write failure unable to another		Flash Memory Failure			29
Contact distributor for service				FP12 out-of-range			N
distributor for service.	nternal hardware problem						
If repeatedly showing this alarm after report contract	Various	Internal software error Vi		Alarm 28 (software)	28 Al	27 :	
It repeatedly showing this alarm after reboot, contact distributor for service.				unused	27 ur	26	
distributor for service.	Various	Ethernet communications problem		Ethernet alarm			
If repeatedly showing this alarm after reboot, contact	various	larms ')					
Contact distributor for service	Damage to current measurement circuit	EEprom detected data packet error( it should recover but will be show vi		Alarm 25 (internal)	25 A	24	
Report controller and allow sweep of array input. Check if				Array current offset			
encountering a derate condition.	Failed current offset routine	ould be zero current, could			24	23	
system design to adjust operating points to prevent	derated mode, full output power not achieved			De-rate limit	D		
Consult documentation for derations of docimal and the	System configuration/design causing the controller to operate in a				23	22	
Contact distributor for service		ailure.					
error may be related to the I2C communications lockup problem with old firmware.	Internal bardwara problem			P3 voltage out of range	22 p	21	
make sure that the unit has the latest A and B firmware - this							
See Fault: Reset above.	Comm EEprom lockup ( Control & Fthernet processors atom tolking)	L		Hatm 11		ľ	
Contact distributor for service	Internal hardware problem	reset has occurred		Controller was reset	20 0	20	
array voltage below maximum rating. Be sure to take into		ADC input max		ADC input max		18	
Consult documentation for maximum array voltage. Keep	Array input voltage too high for safe operation						
Contact distributor for service		'n		High input voltage current limit	18 F	17	
Contact distributor for service	Internal hardware problem						
circuits and unconnected wires.	Hardware failure			MOSFET open P12	17 1	16	
Check all wiring for correct connections shock for the start	Wiring installation error	External system wiring error				1	
correct polarity				unused Miswire	13-14 15	12-13 14	
Ensure Battery Sense and RTS wired to correct the sense of the	Battery Sense and/or RTS wired incorrectly	Remote Temp Sensor wired incorrectly	R/Y - G/Y				
Contact distributor for service.	calibration of measurement circuits not performed at factory			RTS miswire	12	11	
power cables and connection. Inspect Battery		Factory calibration was not performed, inaccurate current and/or		Uncalibrated	H	10	
Inspect Battery Sense connection	Greater than 5V difference between Sense and Battery Voltage						
power cables and connection.	Disconnected wire on the Dattern C	Battery sense was working, now out of range	R/Y - G/Y	Battery sense disconnected	0T	ч	
Inspect Battery Sense connection Inspect Battery sense wires and connection. Inspect Battery	Greater than SV difference between Sense and Battery Voltage			-	5	٥	
Contact distributor for service	Damage to current measurement circuit Disconnected wire on the Battery Sense	Battery sense voltage out of acceptable range	R/Y - G/Y	Battery sense out of range	9	00	
Reboot controller and allow sweep of array input. Check if Alarm returns		lead to inaccurate current measurements				6	
output.	Failed current offset routine	Erroneous current reading when there should be zero current, could		Current offset	00	`	
manual for more information. No action required controller will provide at 6.11 and 4	Input power exceeds controller rating	Active infliting of charging current				1	
temperature is below maximum temp rating of SSMPPT. See				Current limit	7	თ	
Check ambient temperature at the controller location	Excessive ambient temperature						
clearance on all sides. See manual for more information.							
Contact distributor for service.	Poor airflow around controller	reduction of charging current					
prevent the heatsink temperature from exceeding safe levels.		Heatent Link Townson and the second second		High temperature current limit	σ	Ś	
Without accurate temperature sensor, controller cannot	Damage to heatsink temperature sensor						
prevent the heatsink temperature from exceeding safe levels.		Heatsink temp. sensor short circuit		Heatsink temp sensor shorted	ы	4	
Without accurate temperature sensor, controller cannot	Damage to heatsink temperature sensor	measunk temp. sensor open circuit					
See Fault: RTS disconnected above.	active rault, his disconnected above,	Lookalal a		Heatsink temp sensor open	4	ω	
Solutions		Remote Temp Sensor has been disconnected (was properly connected)	R/Y – G/Y	RTS disconnected	ω	2	
			LED Indication	Fault		Bit	

1 2 RTS shorted	0 1 RTS open	Bit Alarm	23 24 Current sensor reference out of range 24-31 25-32 unused	ц ц	17 18	14 15 unused 15 16	13 14 Battery LVD	12 13 RS-232 Serial to Meter Bridge			10 11 Reset		9 10 EEPROM retry limit	8 9 RTS disconnected	¢	00	6 7 Custom settings edit		5 6 DIP switch changed	4 5 array HVD	3 4 Dattery HVD	ω	1 2 FETs shorted	Bit Fault 0 1 overcurrent	TS-MPPT-600V
R/Y – G/Y								R-Y-G		K-Y-G	R-Y-G		R-Y-G	R/Y – G/Y	R/Y - G/Y	K-1-G			R-Y-G	R-Y-G	R – G	R-Y-G	R-Y-G	LED Indication R/Y - G	
Short circuit detected in Remote Temp Sensor	Remote Temp Sensor Disconnected (always set if no RTS connected)		Input current sensor inaccurate and unreliable for correct operation	Internal software error	communications between the power board and control board interrupted and retry limit exceeded Internal software error		Battery voltage below minimum operating range, possible halt to charging possible	TS Meter reprogramming bridge mode failure		Slave mode charging control has timed-out	A power down reset has occurred		EEPROM Communications Problem	Remote Temp Sensor has been disconnected (was properly connected)	Short circuit detected in Remate Temp Sensor	EEPROM settings edited while running			DIP switch changed while running	PV input voltage above safe operating limit	Battery voltage exceeds high voltage disconnect threshold - halt in charging	A software error has occurred in the processor	MOSFETs shorted	ion Description The charge or load current exceeds the controllers rating	
See Fault: RTS shorted above.	RTS not connected		Hardware failure Hardware failure	Various	Various Various		Hardware failure Battery Voltage below controller's minimum operating voltage	Controller has not received a slave command in over 60 seconds TS Meter not accepting firmware update		Loss of communications with controller	Hardware failure Controller has lost nower	EEPROM (long term memory)		causing an erroneous reading The RTS is no longer detected. Previously a valid RTS signal was present	The RTS cable has been pinched or otherwise shorted The RTS terminal connections have collected divertime interview.	A set point was changed via custom programing	Dirt/Debris/Condensation	DIP switch(s) not fully in on/off position	User changed a DIP switch during operation	Power MOSFETs may be shorted Array input voltage exceeds operational ratings	Another charging source in the system is over-charging the battery	Solar input voltage too low This is an internal software problem	The current sense circuitry is malfunctioning A power MOSEET is damaged An external short has occurred	<b>Causes</b> PV Array is too large	
desired for more accurate temperature compensated charging See Fault: RTS shorted above.	RTS not required for operation are one to constant of		Contact distributor for service Contact distributor for service	Contact distribution for non-2-	If repeatedly showing this alarm after reboot, contact distributor for service. Contact distributor for service	vortage. Resize system as necessary to prevent batteries drained below this minimum level.	Consult documentation for minimum battery operating	Check to make sure master device is configured to send slave commands at least once every 60 seconds Refront the difference Build and the state	check master device is still powered and sending commands	None required	Contact distributor for service	Investigate if there is extreme environmental noise present in the vicinity of the TSMPPT. Reboot TSMPPT and see if Fault	<ul> <li>inspect the KTS connection for loose wires. Inspect the RTS cable for breaks.</li> </ul>		may also be used. Inspect RTS cable and connection	corrosion, debris Restart/power cycle to reset. MSView Coil Reset command	Inspect the PCB around the DIP switches for moisture,	PSMPPT so that the new changes take effect. Check all DIP switches to ensure they are in full 'on' or 'off	array voltage below maximum rating. Be sure to take into account temperature effects on the array Voc. Return the DIP switches to original position or reset the	SMPPT charging votage. Somer charging votage. Contact distributor for service Consult documentation for maximum array voltage. Keep	Remove the other charging source, check its operation and charging voltage Veget to charging the source of the sou	wired together Ensure PV Voc is greater than battery voltage Update to latest firmware from the Morningstar wakeita	r anings TriStar Requires Service or replacement Refer to the TriStar MOSFET Replacement instructions Be sure the positive input/output power terminals are not	Solutions Consult the TriStar documentation for maximum current	