Contact distributor for service	Internal hardware problem	Flash memory read/write failure, unable to access memory	tu.	Flash Memory Failure unused	30 31-32	29 30-31
distributor for service. Contact distributor for service	Internal hardware problem	g 12V internal power supply out-of-range. Unit should still correctly, but this is an indication of a potential hardware		FP12 out-of-range	29	28
If repeatedly showing this alarm after r	Various	Internal software error		Alarm 28 (software)	28	27
It repeatedly showing this alarm after r distributor for service.				unused	27	26
distributor for service.	Various			Ethernet alarm	26	25
Contact distributor for service If repeatedly showing this alarm after r	Various	Etprom detected data packet error( it should recover but will be show up on internal log file under Daily Alarms ')				
Alarm returns	Damage to current measurement circuit			Alarm 25 (internal)	25	24
encountering a derate condition.  Reboot controller and allow sweep of a	Failed current offset routine	Erroneous current reading when there should be zero current, could lead to inaccurate current measurements		A	24	23
Consult documentation for deratings. I system design to adjust operating poin	derated mode, full output power not achieved			De-rate limit	1	ŀ
	System configuration/docine				23	22
problem with old firmware. Contact distributor for service	Internal hardware problem	P3 Internal power supply out-of-range. Unit should still operate correctly, but this is an indication of a potential hardware failure	nge	P3 voltage out of range	22	21
error may be related to the I2C commi	(0)					
See Fault: Reset above.	Comm EEprom lockup (Control & Ethernet processors stop talking)	EEPROM Communications Problem				
Contact distributor for service	See Fault: Reset above	A power down reset has occurred	4	Alarm 21	21	20
array voltage below maximum rating. account temperature effects on the ar		ADC input max	•	ADC input max	19	18 19
Consult documentation for maximum						
מיייי ביייי ביייי ביייי אורבי	Array input voltage too high for safe popular.	PV input voltage too high, current limiting to protect hardware	current limit	High input voltage current limit	18	17
Contact distributor for service	Internal hardware problem	correctly but this is an indication of a real to the still operate				
circuits and unconnected wires.	Hardware failure	MOSFET(s) damaged - open circuit		P12	17	16
Check all wiring for correct connection	Wiring installation error	6 61 6		MOSEET ODD	7	15
correct polarity		External system wiring error		Miswire	15	14
Ensure Battery Sense and RTS wired t	battery Sense and/or RTS wired incorrectly			4 unused	13-14	12-13
contact distributor for service.	D)**))		R/Y – G/Y	RTS miswire	12	11
Contact distribute 5	Calibration of measurement circuits not performed at factory	Voltage readings may performed, inaccurate current and/or				-
Inspect Battery sense wires and conn	Greater than 5V difference between Sense and Battery Voltage	Eactory on librarian		Uncalibrated	11	10
Inspect Battery Sense connection	Disconnected wire on the Battery Sense					
inspect Battery sense wires and conr power cables and connection	).	/Y Battery sense was working, now out of range	onnected R/Y - G/Y	Battery sense disconnected	10	9
Inspect Battery Sense connection	Greater than 5V difference between Sense and Battery Voltage					
Contact distributor for service	Damage to current measurement circuit  Disconnected wire on the Ratteny Cance	/Y Battery sense voltage out of acceptable range	of range R/Y - G/Y	Battery sense out of range	9	00
Alarm returns		rear to illactuate current measurements			)	o
output.	Failed current offset routine	Erroneous current reading when there should be zero current, could		carrett offset		
No action required, controller will op	Input power exceeds controller rating			Cirrent officet	<b>x</b> 0	7
temperature is below maximum tem manual for more information.		Active limiting of charging current		Current limit	7	თ
Check ambient temperature at the	Excessive ambient temperature					
clearance on all sides. See manual fo						
Contact distributor for service.	Poor airflow around controller	Heatsink High Temperature Warning, reduction of charging current	current limit	High temperature current limit	σ	
prevent the heatsink temperature (					n	л
prevent the heatsink temperature of Contact distributor for service.	Damage to heatsink temperature sensor	Heatsink temp. sensor short circuit	nsor shorted:	Heatsink temp sensor shorted	и	4
Without accurate temperature sens	o - se merching compensation and sellson					
See Fault: RTS disconnected above		Heatsink temp. sensor open circuit	nsor open	Heatsink temp sensor open	4	ω
Solution	Causes  See Fault: RTS disconnected above	Remote Temp Sensor has beer		RTS disconnected	u	
		ication Description	t LED Indication			Bit

## RTS disconnected above. Solutions

heatsink temperature from exceeding safe levels. curate temperature sensor, controller cannot

heatsink temperature from exceeding safe levels. curate temperature sensor, controller cannot ributor for service.

roller is mounted in a position with enough all sides. See manual for more information.

nore information. e is below maximum temp rating of SSMPPT. See ent temperature at the controller location. Ensure

quired, controller will operate at full rated

roller and allow sweep of array input. Check if

ery sense wires and connection. Inspect Battery and connection.

ry sense wires and connection. Inspect Battery and connection. butor for service.

'y Sense and RTS wired to correct terminals with

ibutor for service ng for correct connections, check for short connected wires.

nentation for maximum array voltage. Keep utor for service erature effects on the array Voc. pelow maximum rating. Be sure to take into

elated to the I2C communications lockup utor for service old firmware. the unit has the latest A and B firmware - this

to adjust operating points to prevent entation for deratings. If desired, evaluate derate condition.

ler and allow sweep of array input. Check if

itor for service

lowing this alarm after reboot, contact owing this alarm after reboot, contact

tor for service owing this alarm after reboot, contact

## TS-MPPT-600V

desired for more accurate temperature compensated charging See Fault: RTS shorted above.	See Fault: RTS shorted above.	Short circuit detected in Remote Temp Sensor	R/Y - G/Y	orted	RTS shorted	2	Н
RTS not required for operation, RTS can be connected if	RTS not connected	Remote Temp Sensor Disconnected (always set if no RTS connected)		oen	RTS open	н	0
				Alarm			Bit
Contact distributor for service				ä	32 unused	1 25-32	24-31
Contact distributor for service	Hardware failure Hardware failure	Input current sensor inaccurate and unreliable for correct operation		Current sensor reference out of		24	23
Contact distributor for service		Internal software error FPGA version not correct and could not be used to		FPGA Version			22
Contact distributor for service	VARIOUS			ed 19-22 (coffuers)		1 19-22	18-21
If repeatedly showing this alarm after reboot, contact distributor for service.		interrupted and retry limit exceeded Internal software error		Fault 17 (software)		17	16
STATE OF THE PROPERTY OF THE P		Communications between the power board and control board		Power-board communication fault	16 Pow		15
voltage. Resize system as necessary to prevent batteries				ed.	15 unused		14
Consult documentation for minimum battery operating	Battery Voltage below controller's minimum operating voltage	charging possible		Battery LVD	Batt		
Retry, try different RI-11 cable, try different TS Meter  Contact distributor for service	Hardware failure	Battery voltage below minimum operating range possible below			14		13
commands at least once every 60 seconds	TS Meter not accepting firmware update	TS Meter reprogramming bridge mode failure	R-Y-G	RS-232 Serial to Meter Bridge	13 RS-2		12
Check to make sure marker decide in the control of	Controller has not received a slave command in over 60 seconds						
check master device is still powered and sending commands							
Check physical communications connection to controlled	Loss of communications with controller	praye induction as timed-out	-				
Contact distributor for service	Controller has lost power	A power down reset has occurred	R-Y-G	Slave Control Timeout	12 Slave		11
returns.	Hardware failure			+			10
Investigate if there is extreme environmental noise present in the vicinity of the TSMPPT. Reboot TSMPPT and see if Earth	EEPROM (long term memory)						
cable for breaks.	Environmental point	EEPROM Communications Problem	R-Y-G	EEPROM retry limit	10 EEP		9
Inspect the RTS connection for loose wires the next to be		neiffole Temp Sensor has been disconnected (was properly connected)	2				
Inspect RTS terminals for dust/dirt/moisture and clean with	causing an erroneous reading	1	S .	RTS disconnected	9 RTS		00
Inspect RTS cable and connection	The RTS cable has been pinched or otherwise shorted	Supply Services in Institute 1 study Selection					
Restart/power cycle to reset. MSView Coil Reset command may also be used	0 c c c c c c c c c c c c c c c c c c c	Short circuit detected in Remote Terms conso	R/Y - G/Y	RTS shorted	8 RTS	7	7
corrosion, debris	A set point was changed via custom programing	EEPROM settings edited while running	R - Y - G	custom settings edit			. ,
Inspect the PCB around the DIP switches for moisture,	Dirt/Debris/Condensation			1	7	טו	o
Check all DIP switches to ensure they are in full 'on' or 'off							
PSMPPT so that the new changes take effect.	DIP switch(s) not fully in on/off position						
Return the DIP switches to original position or reset the	User changed a DIP switch during operation	on switch changes wille funding	:				
array voltage below maximum rating. Be sure to take into		DIP switch changed while	R-Y-G	DIP switch changed	6 DII	И	
Consult documentation for maximum array voltage. Keep	Array input voltage exceeds operational ratings	6					
Contact distributor for service	Power MOSFETs may be shorted	PV input voltage above safe operating limit	R-Y-G	array HVD	5 an	4	
charging voltage. Keep the charging voltage at or below the							
Remove the other charging source, check its operation and	Another charging source in the system is over-charging the battery	battery voltage exceeds high voltage disconnect threshold - halt in charging	2				
Update to latest firmware from the Morningstar website	rins is an interrial software problem		0	battery HVD	4 ba	ω	
Ensure PV Voc is greater than battery voltage	Solar input voltage too low	A software error has occurred in the processor	R-Y-G	software bug	3 sc	2	
Be sure the positive input/output power terminals are not wired together.	The Covilled						
Refer to the TriStar MOSFET Replacement instructions	An external short has occurred						
TriStar Requires Service or replacement	The current sense circuitry is malfunctioning	MOSFETs shorted	R-Y-G	FETs shorted	2 F	1	-
Consult the TriStar documentation for maximum current	000						
Solutions	Causes PV Array is too large	The charge or load current exc	R/Y - G	overcurrent	o D	O	
		ion	LED Indication	Fault		말	